


# ASSEMBLY INSTRUCTION PREMIER SINGLE BED ITEM CODE - 53170

Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart Furniture, Customer Service Free call 1800 351 084




Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart Furniture, Customer Service Free call 1800 351 084




## PRE-ASSEMBLY PREPARATION

#### Before you start:

- 1. Choose a clean, level, spacious assembly area. Avoid hard surfaces that may damage the product
- 2. Take care when lifting. Product should be assembled as near as possible to the point of use
- 3. Ensure that you have all required contents for complete assembly
- 4. Always read the assembly instructions carefully before beginning assembly.
- 5. Keep all hardware parts and packaging out of reach of small children.
- 6. Do not over tighten the screws and bolts as this may damage the threads









Centre Bar x 1pc

Cross Bar x 3pcs

Wooden Slat x 12pcs (905mmx65mmx11mm)

Support Leg x 3pcs

4

5

6

7



(B) M6x30mm bolts x 6pcs



© M6x50mm bolts x 3pcs



DM6 Hex nut x 6pcs




E M4 Allen Key x 1pc (used with M6 bolts)






# **ASSEMBLY..**




### **STEP 2:**



# ASSEMBLY..

# STEP 3:



# **STEP 4:**



## **CARE AND MAINTENANCE**

#### **FURNITURE/ BED**

- 1. When assembling your furniture/ bed please ensure that you have checked the contents for all relevant parts.
- 2. When tightening bolts make sure that they are fully tightened but not forced.
- 3. When moving your fully assembled bed you must first remove the mattress and lift the frame into position, take care when lifting and always have two people handling the bed. PLEASE DO NOT DRAG THE BED as this will cause damage to the rail.
- 4. It is advisable to use approved cleaning products when cleaning the furniture and bed frame as certain chemical based cleaners could have an adverse effect on the bed finish.