


ASSEMBLY INSTRUCTION KRAMER MKII 2 Seat 2RR

ITEM CODE 72144. Imported by Amart Furniture Pty Ltd, Old, Brisbane Australia. For any assistance with assembly or for missing parts please phone

Amart furniture, Customer Service Free call 1800 351 084




Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart Furniture, Customer Service Free Call 1800 351 084

PRE-ASSEMBLY PREPARATION

Before you start:


- 1. Choose a clean, level, spacious assembly area. Avoid hard surfaces that may damage the product
- 2. Take care when lifting. Product should be assembled as near as possible to the point of use
- 3. Ensure that you have all required contents for complete assembly
- 4. Always read the assembly instructions carefully before beginning assembly
- 5. Keep all hardware parts and packaging out of small children
- 6. Do not over tighten the screws and bolts as this may damage the threads






2 **72144**

PARTS LIST




STEP 1

Slide backrest receivers into the steel mechanism posts or the seat (A). Press the backrest evenly down on both sides to lock the backrest into place.




STEP 2



4

ASSEMBLY IS COMPLETE



5 72144

Fabric Care and Maintenance



REGULAR CARE:

• Protect from direct sunlight

"ÁX:a&* ` { Á^* ` |æ|^ Á • ã * Á , Á * &á }

"ÁÜ | cæ*Á^c^!• ãa|^ Á& • @ā } • Á^* |æ|^

CLEANING:

″ÁÖ[Á,[cÁ,^{ [ç^Á& • @]}Á& [ç^!•Á; !Á,^] æ æ Æ Á& ^æ j j * Á, ç^} Ác@ * @ they may have zippers

″ÁÖ[Á,[ơÁ, æ; ΘΘΕ̈́Ö[Á,[ơÁs¦^Á&,^æ) Ε̈́Ö[Á,[ơÁ, Θæ;][[Á&,^æ)

"ÁÔ|^æ) Á, ão@ÁQ oÁ, æe^¦Ár¢dæ&dā[}Á(æ&@), ^ÈÁÚ¦[△••ā[}æjÁ&|^æ) ā;*
recommended

″ÁÖ[Á,[ơÁ•^Ásãa@, æ•@ð,*Áã ઁãaÁ,¦Áæě}å¦^Ás^♂*^}c

"ÁV•^Á;}|^Á]@[•♂¦^Áå^♂¦*^}o•

"ÁÖ[Á[oÁ^oÁā]ā *

"ÁÖ!^ÁŞIÁ @æå^Áæç æêÁ¦[{Áåã^&oÁ@ ææÁæ}åÁ*}|ãt@c

"ÁŒ|[Ág Áå¦^Ás@|:[* @ Áà^-; ¦^Á^Ë •^

SPOT CLEANING:

″ÁÖ[Á,[ơÁ*à

″ÁÖ[Á,[œÁ][œÁs|^æ)Á,ão@Áse)^Á;[∣ç^}c

"Á\'^ææÁ|ā∥•Áæ}åÁ;œã,•Áæ Á[[}Áæ Á[••ãa|^

"ÁÕ^} d^Á & að ^Á, -Áæ)^Á[āÁ, kí []Áæ)^Áã `ãáÁ; [{Ác@ Á`;-æ&^Á, -Ác@ fabric

"ÁŒ] | ^Á; | [] | â^œà ^Á&|^æ) ā, *Áæ* ^} æ Á dæ å, 'Áæ å, *Á[Áā, • d *&æ å] •Á[remove the residue of the spill

ÄDo not saturate the fabric or interior with water or other cleaning liquids **WARNING**:

Apply only water-based soil resist (fabric protection) treatments. Do not use aerosol products

- * PILLING IS NOT A FABRIC DEFECT OR FAULT AND IS NOT COVERED BY WARRANTY
- * PILLING IS A NORMAL OCCURRENCE CAUSED BY WEAR AND TEAR AND DOES NOT AFFECT THE DURABILITY OR FUNCTIONALITY OF THE FABRIC AND IS EASILY REMOVED