




## ASSEMBLY INSTRUCTION

LORAS 5 SEATER CORNER

ITEM CODE 67772

Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia.

For any assistance with assembly or for missing parts please phone  
Amart Furniture, Customer Service Free call 1800 351 084




Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia.

For any assistance with assembly or for missing parts please phone  
Amart Furniture, Customer Service Free call 1800 351 084


## PRE-ASSEMBLY PREPARATION

### Before you start:

1. Choose a clean, level, spacious assembly area. Avoid hard surfaces that may damage the product
2. Take care when lifting. Product should be assembled as near as possible to the point of use
3. Ensure that you have all required contents for complete assembly
4. Always read the assembly instructions carefully before beginning assembly.
5. Keep all hardware parts and packaging out of reach of small children.
6. Do not over tighten the screws and bolts as this may damage the threads







## PARTS LIST








PART I

PART II

## Hardware

HARDWARE LIST		
NO.	DESCRIPTION	QTY
A	Socket head screw  M10x45	4 PCS
B	Inclined Sofa Legs 	4 PCS
C	Allen Key 	1 PC
F	screw  M4x60	16 PCS

PART I

HARDWARE LIST		
NO.	DESCRIPTION	QTY
A	Socket head screw  M10x45	4 PCS
B	Inclined Sofa Legs 	4 PCS
C	Allen Key 	1 PC
D	Plastic Support Leg 	1 PC
F	screw  M4x60	16 PCS

PART II


PLEASE TAKE NOTE:

PIECES REQUIRED FOR ASSEMBLY ARE LOCATED INSIDE THE DUST COVER UNDERNEATH SOFA


## Step 1

DETAILS (1) - Align base plate of each foot (B) with the pre-threaded holes in the undersides of the sofa as shown in the below diagram. Insert Bolt (A ) and tighten by turning clockwise using Allen key (C) . Insert Screw (F) using screwdriver.

### PART I



## Step 2 PART I ASSEMBLY COMPLETED



**IMPORTANT:**


**PLEASE ENSURE FEET ARE TIGHTENED SECURELY BEFORE USE!**

## Step 3


DETAILS (1) - Align base plate of each foot (B) with the pre-threaded holes in the undersides of the sofa as shown in the below diagram. Insert Bolt (A) and tighten by turning clockwise using Allen key (C) . Insert Screw (F) using screwdriver.

DETAILS (2) - Align bottom for foot (D) with pre-threaded holes in the middle of the undersides of the lounge and tighten by turning clockwise.


## PART II




## Step 4 PART II ASSEMBLY COMPLETED



## Step 5 SECURE PART I TO PART II BY ALIGNING CLIPS CONNECTING THE PIECES TOGETHER



## Step 6 ASSEMBLY COMPLETED



**IMPORTANT:**  
PLEASE ENSURE FEET ARE TIGHTENED SECURELY BEFORE USE!

# FABRIC PRODUCT CARE



## REGULAR CARE:

- Protect from direct sunlight
- Vacuum regularly using low suction
- Rotate reversible cushions regularly
- Avoid exposure to new clothing, cushions or throws as this may lead to dye transfer and permanent staining

## CLEANING:

- Do not remove cushion covers for separate cleaning even though they may have zippers
- Do not wash, Do not dry clean, Do not shampoo clean
- Clean only with hot water extraction machine. Professional cleaning recommended
- Do not use dishwashing liquid or laundry detergent. Use only upholstery detergents
- Do not wet filling
- Dry in shade away from direct heat and sunlight
- Allow to dry thoroughly before re-use

## SPOT CLEANING:

- Do not rub
- Do not spot clean with any solvent
- Treat spills and stains as soon as possible
- Gently scrape off any soil or blot any liquid from the surface of the fabric before applying cleaner
- Apply proprietary cleaning agents strictly according to instructions to remove the residue of the spill
- Do not saturate the fabric or interior with water or other cleaning liquids

## WARNING:

Apply only water-based soil resist (fabric protection) treatments. Do not use aerosol products

\* PILLING IS NOT A FABRIC DEFECT OR FAULT AND IS NOT COVERED BY WARRANTY

\* PILLING IS A NORMAL OCCURRENCE CAUSED BY WEAR AND TEAR AND DOES NOT AFFECT THE DURABILITY OR FUNCTIONALITY OF THE FABRIC AND IS EASILY REMOVED