


ASSEMBLY INSTRUCTION KIDZ MK2 DOUBLE BUNK BED ITEM CODE - 64838

Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart Furniture, Customer Service Free call 1800 351 084



Important:

DUE TO THE SIZE OF THIS UNIT, WE RECOMMEND THAT ASSEMBLING IS DONE IN THE ROOM INTENDED FOR USE AND ASSEMBLED BY TWO PEOPLE.

WARNING:

TOP BUNK AND ELEVATED BEDS ARE DANGEROUS AND ARE NOT RECOMMENDED FOR CHILDREN UNDER THE AGE OF 9

Falls from elevated beds can be fatal and deaths have occurred where children have fallen from elevated beds. this is relevant for all ages. The risk is greater for younger children.

The risk of injury or death from a fall from an elevated bed compared to a non-elevated bed is:

10 x greater for 7-8 year olds 7 x greater for 9-10 year olds 3 x greater for 11-12 year olds

WARNING:


The upper bunk must be more than 2m from any ceiling fan.



PRE-ASSEMBLY PREPARATION

Before you start:

- Choose a clean, level, spacious assembly area. Avoid hard surfaces that may damage the product
- 2. Take care when lifting. Product should be assembled as near as possible to the point of use
- 3. Ensure that you have all required contents for complete assembly
- 4. Always read the assembly instructions carefully before beginning assembly.
- 5. Keep all hardware parts and packaging out of reach of small children.
- 6. Do not over tighten the screws and bolts as this may damage the threads






To help prevent serious or fatal injuries from entanglement or falls:


- Use the correct size mattress as specified
- Upper surface of mattress must be at least 160mm below upper edge of guard rails
- Follow all written instructions included with this bed
- . Use guardrails on both sides of upper bunk
- Check the bunk bed periodically to ensure that the guardrails, access device and other components are maintained in the correct position and state of repair and that all connectors are tight with nothing protruding more than 8mm
- . Ensure the upper bunk is more than 2m from any ceiling fan
- Prohibit horseplay on under bed
- Prohibit more than one person on the upper bunk


TOP BUNKS AND ELEVATED BEDS ARE DANGEROUS AND ARE NOT RECOMMENDED FOR CHILDREN UNDER THE AGE OF 9.

DO NOT REMOVE THIS LABEL













ASSEMBLY..

STEP 1a: Attach Upper Bunk Back Siderail (5) with Cross Bar (9) and Centre Bar (10) to Upper Bunk Front Siderail (6)



STEP 1b: Place the siderails at an angle as shown. Starting with one side, insert the wooden slats into the slots. Do the same for the other side.




STEP 2:

Assembling the Lower Bunk Bedbase.


Repeat STEP 1a to 1b by using 7891012

ASSEMBLY..

STEP 3: Attach Upper & Lower Bunk Bedbase to Left End Frame (1) & Right End Frame (2)



STEP 4: Attach the Ladder 11 to the Upper Front Siderail 6 and Lower Front Siderail 8



ASSEMBLY..

STEP 5: Attach the Back Guardrail 3 to Left/Right Frame 1 2 and Upper Back Siderail 5 Attach the Front Guardrail 4 to Left Frame 1 and Upper Front Siderail 6 Attach the Handrail (13) to Front Guardrail (4) and Right Frame 2



Check and tighten all bolts before use.

Warning:

During service, check the fastenings regularly and retighten as necessary. It is also adviced that any person sleeping on the bottom bunk should have their head at opposite end of the bed to the ladder.

Assembly Is Complete



CARE AND MAINTENANCE

FURNITURE/ BED

- 1. When assembling your furniture/ bed please ensure that you have checked the contents for all relevant parts.
- 2. When tightening bolts make sure that they are fully tightened but not forced.
- 3. When moving your fully assembled bed you must first remove the mattress and lift the frame into position, take care when lifting and always have two people handling the bed. PLEASE DO NOT DRAG THE BED as this will cause damage to the rail.
- 4. It is advisable to use approved cleaning products when cleaning the furniture and bed frame as certain chemical based cleaners could have an adverse effect on the bed finish.