


ASSEMBLY INSTRUCTION BILLIE QUEEN BED ITEM CODE 72024

Imported by Amart Furniture Pty Ltd, Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart furniture, Customer Service Free call 1800 351 084




Imported by Amart Furniture Pty Ltd,Qld, Brisbane Australia. For any assistance with assembly or for missing parts please phone Amart Furniture, Customer Service Free Call 1800 351 084

1


PRE-ASSEMBLY PREPARATION


Before you start:


- 1. Choose a clean, level, spacious assembly area. Avoid hard surfaces that may damage the product
- 2. Take care when lifting. Product should be assembled as near as possible to the point of use
- 3. Ensure that you have all required contents for complete assembly
- 4. Always read the assembly instructions carefully before beginning assembly
- 5. Keep all hardware parts and packaging out of small children
- 6. Do not over tighten the screws and bolts as this may damage the threads




PARTS LIST








STEP 1 Attach Metal bracket(9) to Headboard(1), using spring washer(H) flat washer(A), and bolt(C) as shown below, then tighten with allen key(B).



$\label{eq:STEP2} \textbf{Attach Metal bracket(9) to Foot end of Side rails, using spring washer(H) flat washer(A), and bolt(C) as shown below, then tighten with allen key(B).}$




STEP 3


Attach Rails(2,3) to Metal bracket on Headboard(1), using spring washer(H)Flat washer(A), and bolt(C) as shown below, then tighten with allen key(B).

Then attach bracket on Rails(2,3) to Footboard(4), using spring washer(H) flat washer(A), and bolt(C) as shown below, then tighten

with allen key(B).




Attach Centre slat rail(7) to Headboard(1) and Footboard(4), using flat washer(A) and bolt(C) as shown below, then tighten with allen key(B).




STEP 5


Using two people, carefully turn the bed onto its side. Align Legs(6)with pre-drilled holes, and attach using spring washer(H) flat washer(A), and bolt(E) as shown below, then tighten with allen key(B). Then align screw(D) with the hole and tighten.




 $\begin{tabular}{ll} STEP 6 \\ \hline \begin{tabular}{ll} Attach Centre support legs(5) to centre slat rail(7), using flat washer(A)nut(F), and bolt(C) as shown below, then tighten with allen key(B) and wench(G). \\ \hline \end{tabular}$



 $\begin{center} {\bf STEP 7} \\ {\bf Attach Slats (8) to side rails(2,3), using screw(D).} \\ \end{center}$



ASSEMBLY IS COMPLETE



Fabric Care and Maintenance



 $\tilde{AU}[\cos^{\wedge}A^{\wedge}c^{\wedge}] \cdot \tilde{aa}[\wedge A\hat{s}] \cdot \tilde{aa}] \cdot A\hat{s}$

CLEANING:

~ÁÖ[Á,[cÁ^{ [ç^Á& • @)]} Á&[ç^¦•Á[¦Á^]æ æ æ Á&|^æ) ð * Á^ς^} Áσ@ * @ they may have zippers

″ÁÖ[Á,[σÁ, ææ @ÉÄÖ[Á,[σÁ&¦^Á&|^æ) ÉÄÖ[Á,[σÁ @æ{][[Á&|^æ)

″ÁÔ|^æ) Á, ão@ÁQ oÁ, æe^¦Án¢dæ&dã[}Á(æ&@), ^ÈÁÚ¦[-△••ã[}æþÁ&|^æ);ã,* recommended

″ÁÖ[Á,[œÁ•^Áåã@ææ@a,*Áã ăãÁ,¦Áæ;}å¦^Áå^œ^¦*^}c

~ÁN•^Á;}|^Á]@|•ơ\|^Áå^ơ\|*^}•

*"Á*Ö[Á[oÁ^oÁðilði*

"ÁÖ¦^Á§IÁ @æå^Áæ; æêÁ¦[{Áåã^&oÁ@ æaÁæ}åÁ`}|ã @c

"ÁŒ|[Ág Áå¦^Áœ@ ¦[* @ Áà^+; ¦^Á^Ë •^

SPOT CLEANING:

″ÁÖ[Á,[cÁ,`à

~Á√¦^ænÁ•]ã|•Ása)åÁ•œæã,•ÁsæÁ•[[}ÁsæÁ,[••ãà|^

~ÁÕ^} d^Án&læ}^Án,~Áse)^Án[āμÁ,lÁn[]Áse)^Áã ˘ããÁl;[{Ás@\Á`l~æ&ΛÁ,Άs@\ fabric before applying cleaner

"ÁOE] | ^ Á; | [] | 21 czel ^ Á&| ^ zzel ^ Á&| ^ zzel ^ } o Á; d 28d ^ Áze8&[| å 2] * Áţ Áţ • d * &c4] } • Áţ remove the residue of the spill

ÄDo not saturate the fabric or interior with water or other cleaning liquids **WARNING:**

Apply only water-based soil resist (fabric protection) treatments. Do not use aerosol products

- * PILLING IS NOT A FABRIC DEFECT OR FAULT AND IS NOT **COVERED BY WARRANTY**
- * PILLING IS A NORMAL OCCURRENCE CAUSED BY WEAR AND TEAR AND DOES NOT AFFECT THE DURABILITY OR FUNCTIONALITY OF THE FABRIC AND IS EASILY REMOVED